


Performance report

Finger Lakes Instrumentation, L.L.C. Proline CCD Camera - FLI CCD Camera



Report information

Scale	(8,93 /)
Units	/

Summary

	-	PC
	31	
(/)	0,06	8,93
(/)	0,00	4,6

URB

()	15285	18709908
Bulk+Interrupt ()	15285	18709908
Isochronous ()	0	0
Control ()	0	0

Table report

Time	-	PC
0	0	0
0,5	0	0
1	0	0
1,5	0	0
2	0	0
2,5	0	0
3	0	0
3,5	0	0
4	0	0
4,5	0	0
5	0,04	0,09
5,5	0,06	0,12
6	0,06	0,12
6,5	0,06	0,12
7	0	6,95
7,5	0	7,94
8	0	8,93
8,5	0	8,93
9	0	8,93
9,5	0	7,94
10	0	8,93
10,5	0	8,93
11	0	8,93
11,5	0	8,93

12	0	7,94
12,5	0	8,93
13	0	8,93
13,5	0	8,93
14	0	8,93
14,5	0	7,94
15	0	8,93
15,5	0	8,93
16	0	8,93
16,5	0	8,93
17	0	7,94
17,5	0	8,93
18	0	8,93
18,5	0	8,93
19	0	8,93
19,5	0	7,94
20	0	8,93
20,5	0	8,93
21	0	8,93
21,5	0	8,93
22	0	7,94
22,5	0	8,93
23	0	8,19
23,5	0	0
24	0	0
24,5	0	0
25	0	0
25,5	0	0
26	0	0
26,5	0	0
27	0	0
27,5	0	0
28	0	0
28,5	0	0
29	0	0
29,5	0	0
30	0	0
30,5	0	0
31	0	0